

E I F S P O R T O B E L L O ?

WHAT?


EIFS (Exterior Insulation and Finish Sytems a.k.a. Synthetic Stucco) clad residences

WHERE?

Chicago, Illinois
& St. Charles, Illinois

INFO:

This 3 year old Chicago Home is part of a very large development. All of these homes have potential structural damage, moisture infiltration, and associated environmental health hazards.



Mushroom/ fungi growing at window head due to elevated moisture levels

R O T T I N G / W E T W O O D

INFO:

St. Charles Home Built 1995-96 occupied April 1996. Home shows severe moisture penetration and saturation. When tested for moisture , the wood structure beneath has a 42% moisture content. (Much higher than the normal 8% -12%.)



This ad is for all the home builders and architects in the Midwest who state that "Problem EIFS jobs are just a localized problem in North Carolina"